

References

Executive Summary

- Joint Pipeline Office Work Plan (2001)
- U.S. Department of the Interior, “Agreement and Grant of Right-of-Way for Trans-Alaska Pipeline between the United States of America and Amerada Hess Corporation, ARCO Pipe Line Company, Exxon Pipeline Company, Mobil Alaska Pipeline Company, Sohio Pipe Line Company and Union Alaska Pipeline Company,” Government Printing Office, O-531-651, Washington, D.C. (1974)
- State of Alaska, Department of Natural Resources, “State Right-of-Way Lease for the Trans-Alaska Pipeline between the State of Alaska and Amerada Hess Corporation, ARCO Pipeline Company, Exxon Pipeline Company, Mobil Alaska Pipeline Company, Sohio Pipeline Company and Union Alaska Pipeline Company,” ADNR, Juneau, Alaska (1974)
- JPO Surveillance Report No. FBU-01-S-001, “Pipe Movement at Milepost 170,” Stipulations 1.18.1 and 1.21.1, (November 2, 2000)
- JPO Surveillance Report No. ANC-02-S-337, “Walking Working Surface Requirements,” Stipulation 1.20, (March 13, 2002)
- JPO Surveillance Report No. JPO-00-S-033, “Verification of the Implementation of Internship Opportunities and Programmatic Components of the October 1999 Revision of the Alaska Native Utilization Agreement and the January 1999 ANUA Implementation Plan,” Federal Grant Section 29, (June 14, 2000)
- JPO Technical Report No. ANC-01-E-008, “Performance of the APSC Earthquake Monitoring System,” Stipulation 3.4.1.2, (December 18, 2001)
- JPO Technical Report No. ANC-02-E-002, “Earthquakes and Fault Displacements,” Stipulation 3.4.1.2, (February 26, 2002)
- JPO Assessment Report No. JPO-00-A-006, “Assessment of Alyeska Pipeline Service Company’s Supplier Evaluation Processes for Compliance to Grant and Lease Requirements,” Federal Grant Section 9, State Lease Section 16, (September 2000)
- JPO Assessment Report No. ANC-01-A-003, “Evaluation of Alyeska Pipeline Service Company’s Compliance With the Federal Grant and State Lease, Supplier Evaluation Process,” Federal Grant Section 9, State Lease Section 16, (October, 2001)

CHAPTER 1

- JPO CMP Report, “Alyeska Pipeline Service Company’s TAPS Environmental Protection Program,” (March 1998)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s TAPS Employee Safety Program,” (April 1998)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s Project Performance for TAPS,” (September 1998)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s Operation of the Trans-Alaska Pipeline System,” (February 1999)
- JPO CMP Report, “An Evaluation of Selected Portions of the TAPS Maintenance Program, January 1997-April 1999,” (April 1999)
- JPO CMP Report, “Trans-Alaska Pipeline Construction Program 1999/2000,” (January 2001)
- JPO CMP Report, “Operation of the Trans-Alaska Pipeline 1999/2000,” (January 2001)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” (January 2001)
- JPO Annual Report, (1994)
- JPO Annual Report, (1995)
- JPO Annual Report, (1996)
- JPO Annual Report, (1997)
- Joint Pipeline Office, “Agreement to Support the State-Federal Joint Pipeline Office,” signed by the eleven state and federal JPO agencies, (January 26, 1994)
- Mineral Leasing Act as amended, 30 U.S.C., (1920)
- Trans-Alaska Pipeline Authorization Act, 30 U.S.C, Public Law 93-153, 93rd Congress, S. 1081, U.S. House of Representatives, Washington, D.C., (November 1973)
- Alaska Statute, Title 38, Public Land, Chapter 35, Right-of-Way Leasing Act (AS 38.35)
- U.S. Department of Transportation, Office of Pipeline Safety, Title 49, Code of Federal Regulations, Section 195

- U.S. General Accounting Office (GAO) Report, “Actions to Improve Safety are Under Way,” GAO/RCED-95-162, (August 1995)
- U.S. Department of the Interior and Alyeska Pipeline Service Company Memorandum of Agreement, “Alaska Native Utilization Agreement between the, U.S. Department of the Interior and Alyeska Pipeline Service Company,” (October 20, 1995)
- Alyeska Pipeline Service Company, “Pipeline Oil Discharge Prevention and Contingency Plan,” CP-35-1, Edition 4, Rev. 0, Section 1.3.3, (December 31, 2001)

CHAPTER 2

- JPO Assessment Report No. ANC-02-A-005, “Federal Agreement and Grant Legal and Administrative Provisions,” (March 2002)

Federal Grant Section 8 – Use Charge for Right of Way

- JPO Surveillance Report No. ANC-02-S-006, “Verification of Permittee Compliance with Section 8, Use Charge of Right-of-Way, Federal Agreement and Grant,” (March 6, 2002)

Federal Grant Section 9/ State Lease Section 16 - Construction Plans and Quality Assurance Program

- JPO Technical Report No. JPO-01-E-001, “Investigation of the Spark Incident at the Valdez Marine Terminal,” (December 2000)
- JPO Technical Report No. JPO-00-E-031, “JPO Accident Investigation of the Valdez Marine Terminal Fatality of August 16, 2000,” (November 20, 2000)
- JPO Assessment Report No. JPO-00-A-006, “Assessment of Alyeska Pipeline Service Company’s Supplier Evaluation Processes for Compliance to Grant and Lease Requirements,” Federal Grant Section 9, State Lease Section 16, (September 2000)
- JPO Assessment Report No. ANC-01-A-003, “Evaluation of Alyeska Pipeline Service Company’s Compliance With the Federal Grant and State Lease, Supplier Evaluation Process,” Federal Grant Section 9, State Lease Section 16, (October, 2001)
- JPO Assessment Report No. ANC-01-011, “Assessment of Compliance With ADF&G Requirements and Grant and Lease Stipulation 2.5, Fish & Wildlife Protection,” (November 2001)
- JPO Assessment Report No. JPO 00-A-001, Alyeska Pipeline Service Company Compliance With Fish Passage and Related Environmental, Surveillance, Maintenance and Quality Program Requirements,” (February 2000)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” p.12, (January 2001)
- JPO CMP Report, “Trans-Alaska Pipeline Construction Program 1999/2000,” pp. 33-34, (January 2001)
- JPO and Alyeska Pipeline Service Company Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- JPO Letter No. 01-187-DG, to APSC, Re: “Proposed QA-36, Revision 10,” (December 14, 2001)
- JPO Letter No. 99-055-JS, to APSC, Re: “APSC Plans to Develop a Revised Quality Program Manual,” (June 15, 1999)
- Det Norske Veritas (DNV), “Progress Review Report, ROWR Compliance Audit of Alyeska Pipeline Service Company,” prepared for the Trans-Alaska Pipeline System Owners, Project No. 10561-C, Copy Number 1, (March 2001)
- Det Norske Veritas (DNV), “ROWR Compliance Audit of Alyeska Pipeline Service Company, Progress Review (Systems Finds) Report,” prepared for the Trans-Alaska Pipeline System owners project No. 10561-E (March 2002)

Federal Grant Section 10 – Compliance With Notices to Proceed

- JPO Technical Report No. FBU-02-E-001, “Compliance Verification with Notices to Proceed, Section 10 of the Federal Grant, and Section 23 of the State Lease,” (January 2002)
- JPO Assessment No. JPO-00-A-004, “Alyeska Pipeline Service Company, 1999 Flood Damage Repair Project, F-075,” (June 2000)
- JPO Letter No. 97-074-JS, to APSC, Re: “JPO Policy to Implement Notice to Proceed (NTP) Process For Work on TAPS at the Valdez Marine Terminal, Pump Stations and the Mainline Pipe,” (October 7, 1997)

Federal Grant Section 12 – Reimbursement of Department Expenses

- JPO Surveillance Report No. ANC-02-S-008, “Verification of Permittee Compliance with Federal Grant Section 12, Reimbursement of Department Expenses,” (March 6, 2002)

Federal Grant Section 13 – Damage to U. S. Property; Repair, Replacement or Claim for Damages

- JPO Surveillance Report No. ANC-02-S-009, “Verification of Permittee Compliance With Federal Grant, Section 13, Damage To United States Property, Repair, Replacement or Claim for Damages,” (March 6, 2002)

Federal Grant Section 15 – Guaranty

- JPO Surveillance Report No. ANC-02-S-010, “Verification of Permittee Compliance with Federal Grant, Section 15, Guaranty,” (March 8, 2002)

Federal Grant Section 16 – Laws and Regulations

- JPO Surveillance Report No. ANC-02-S-011, “Verification of Permittee Compliance with Federal Grant, Section 16, Compliance With Federal Laws and Regulations,” (March 8, 2002)
- JPO Assessment Report No. ANC-01-A-009, “Assessment of Operations Material Sites on TAPS,” (October 2001)
- U.S. Coast Guard Letter to the BLM Authorized Officer, Re: “Comprehensive Safety Assessment of Portions of TAPS under Coast Guard Jurisdiction,” (June 14, 2001)
- U.S. Environmental Protection Agency (EPA) Letter to the BLM Authorized Officer, Re: “Renewal of Federal TAPS Right-of-Way,” (August 29, 2001)
- Alaska Department of Environmental Conservation (ADEC) Report, “A Comparison of Alaska Department of Environmental Conservation Authorities and the State of Alaska Right-of-Way Lease for the Trans-Alaska Pipeline System,” (January 28, 2002)
- U.S. Department of the Interior, Code of Federal Regulations, Title 43, Public Lands Interior, Section 3600, Mineral Materials Disposal; Section 3610, Mineral Material Sales; Section 3620, Free Use
- Mineral Leasing Act as amended, 30 U.S.C., (1920)
- U.S. Department of Transportation, office of Pipeline Safety, Research and Special Programs Administration, Letter to BLM Authorized Officer, Re: “Summary of TAPS Non-Compliance and Enforcement Record as of February 2002,” April 15, 2002.
- Trans-Alaska Pipeline Authorization Act, Public Law 93-153, 93rd Congress, S. 1081, U.S. House of Representatives, Washington, D.C., (November 1973)
- Federal Water Pollution Control Act, as amended, 33 U.S.C. § 1321 *et seq.*
- Clean Water Act, as amended, 33 U.S.C. (1972)
- Rivers and Harbors Act, 33 U.S.C., 403, Section 10, (1899)

Federal Grant Section 22 – Transfer

- JPO Surveillance Report No. ANC-02-S-014, “Verification of Permittee Compliance With Federal Grant, Section 22, Transfers of Interest,” (March 6, 2002)

Federal Grant Section 24 – Duty of Permittees to Abate

- JPO Technical Report No. VMT-02-E-001, “Engineering Report on Berths 4 and 5, Tanker Vapor Control System, RCM Progress,” (January 30, 2002)
- JPO Technical Report No. JPO-00-E-031, “JPO Accident Investigation of the Valdez Marine Terminal Fatality of August 16, 2000,” (November 20, 2000)
- JPO Technical Report No. FBU-01-E-006, “Stipulation 2.7, Clearing,” (July 18, 2001)
- JPO Assessment Report No. ANC-01-A-015, “Assessment of Compliance with ADF&G Requirements and Grant and Lease Stipulation 2.12, Restoration,” (November 2001)
- JPO Assessment Report No. ANC-01-011, “Assessment of Compliance With ADF&G Requirements and Grant and Lease Stipulation 2.5, Fish & Wildlife Protection,” (November 2001)
- JPO Assessment Report No. ANC-02-A-003, “An Evaluation of Alyeska Pipeline Service Company’s Compliance With Grant and Lease Stipulation 2.2, Pollution Control,” (February 2002)
- JPO Assessment Report No. ANC 02-A-001, “Evaluation of Agreement and Grant of Right-of-Way and Right-of-Way Lease Stipulation 1.20, Health and Safety,” (February 2002)
- CMP Report, TAPS Maintenance Program 1999/2000 pp. 21, 34-35, 37-38, (January 2001)
- JPO Letter No. 02-004-DG, to APSC, Re: “Closure of Notice, Compulsory Redesign of the Valdez Marine Terminal Vapor Control System, Letter No. 99-033-LB,” (February 11, 2002)
- JPO and Alyeska Pipeline Service Company Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,”

(February 28, 2002)

- State and Federal Interagency and Alyeska Pipeline Service Company Report, “Joint After-Action Report for the TAPS Bullet Hole Response of October 2001,” (February 8, 2002)
- U.S. Coast Guard Final Report, “Safety Assessment, Marine Portion of the Trans Alaska Pipeline System, Conducted December 2000,” p. 43, (December 2000)

Federal Grant Section 28 - Nondiscrimination and Equal Employment Opportunity

- JPO Assessment Report No. ANC-01-A-004, “Federal Agreement and Grant of Right-of-Way, Section 28, Nondiscrimination and Equal Employment Opportunity,” (February 4, 2002)

Federal Grant Section 29 – Training of Alaska Natives

- JPO Surveillance Report No. JPO-00-S-033, “Verification of the Implementation of Internship Opportunities and Programmatic Components of the October 1999 Revision of the Alaska Native Utilization Agreement and the January 1999 ANUA Implementation Plan,” Federal Grant Section 29, (June 14, 2000)
- JPO Letter No. 02-002-CHC, to APSC, Re: “Discharge Notification,” (January 15, 2002)
- JPO Letter No. 02-014-DG, to APSC, Re: “Discharge Notification,” (March 6, 2002)
- U.S. Department of the Interior and Alyeska Pipeline Service Company, “Alaska Native Utilization Agreement between the U.S. Department of the Interior and Alyeska Pipeline Service Company,” (October 20, 1995)
- U.S. Department of the Interior and Alyeska Pipeline Service Company, “Alaska Native Utilization Agreement between the U.S. Department of the Interior and Alyeska Pipeline Service Company,” (1998)
- U.S. Department of the Interior and Alyeska Pipeline Service Company, “Alaska Native Utilization Agreement between the U.S. Department of the Interior and Alyeska Pipeline Service Company,” (October 15, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 02-18153, Re: “Implementation Plan for Alaska Native Utilization Agreement,” (January 31, 2002)
- Alyeska Pipeline Service Company, Government Letter No. 02-18154, Re: “Section 29 Year End Average Statistics for 2001,” (January 31, 2002)

State Lease Legal and Administrative Provisions

- JPO Assessment Report No. ANC-02-A-006, “State Right-of-Way Lease Legal and Administrative Provisions,” (March 2002)

State Lease Section 3 – Rental

- JPO Surveillance Report No. ANC-02-S-024, “Verification of Lessee Compliance With State Lease, Section 3, Rental,” (March 12, 2002)
- Alaska Department of Natural Resources (ADNR), State Pipeline Coordinator’s Office, Letter to Alyeska Pipeline Service Company, Re: “TAPS Appraisal Review Statement Summary of Appraisal No. 2973,” (December 21, 2001)
- Alyeska Pipeline Service Company, Letter to Alaska Department of Natural Resources (ADNR), Letter No. 02-18105, Re: “TAPS Right-of-Way Appraisal No. 2973,” (January 16, 2002)

State Lease Section 9 – Compliance With State Laws and With Regulations and Orders of the Alaska Pipeline Commission

- JPO Surveillance Report No. ANC-02-S-030, “Verification of Lessee Compliance With State Lease, Section 9, Compliance With State Laws and Regulations and Orders of the Alaska Pipeline Commission,” (March 12, 2002)
- JPO Assessment Report No. ANC-01-A-011, “Assessment of Compliance With ADF&G Requirements and Grant and Lease Stipulation 2.5, Fish and Wildlife Protection,” (November 2001)
- JPO Assessment Report No. ANC-01-A-009, “Assessment of Operations Material Sites on TAPS,” (October 2001)
- State of Alaska, Regulatory Commission of Alaska report, “Trans-Alaska Pipeline System Violations of AS 42.06 Since 1999, TAPS Compliance Report,” (November 19, 2001)
- Alaska Department of Environmental Conservation (ADEC) compliance report, “A Summary of Alaska Department of Environmental Conservation Enforcement Actions Involving Alyeska Pipeline Service Company, From 1999 Through 2001,” (January 2002)
- Alaska Department of Natural Resources (ADNR), Office of History and Archaeology, Division of Parks and Outdoor Recreation Report, “Evaluation of the Trans-Alaska Pipeline System Compliance With Cultural Resource Laws and Regulations, (December 2001)

- Alaska Department of Labor (ADOL), Memorandum to Alaska Department of Natural Resources (ADNR), Re: “TAPS Lease Renewal Compliance Report,” (January 7, 2002)
- U.S. Environmental Protection Agency (EPA) Letter to the BLM Authorized Officer, Re: “Renewal of Federal TAPS Right-of-Way,” (August 29, 2001)
- Alaska Administrative Code (AAC), Title 5, Fish and Game, Chapter 95, Fish and Game Habitat
- Alaska Administrative Code (AAC), Title 6, Governor’s Office, Chapter 80, Fees for Department Services
- Alaska Administrative Code (AAC), Title 11, Natural Resources
- Alaska Administrative Code (AAC), Title 13, Chapters 50-55, Building Code, Fire Code, Mechanical Code
- Alaska Statute (AS), Title 16, Section 16.05.840, Fishway Required
- Alaska Statute (AS), Title 16, Section 16.05.870, Protection of Fish and Game
- Alaska Statute (AS), Title 18.70, Fire Protection
- Alaska Statute (AS), Title 27.19, Reclamation and Mining
- Alaska Statute (AS), Title 38, Issuance of Land Use Permits
- Alaska Statute (AS), Title 41, Public Resources
- Alaska Statute (AS), Title 41.35, The Alaska Historic Preservation Act of 1971
- Alaska Statute (AS), Title 42.06, The Pipeline Act
- Alaska Statute (AS), Title 46, Water, Air, Energy and Environmental Conservation

State Lease Section 11 – Transfer, Assignment, or Other Disposition

- JPO Surveillance Report No. ANC-02-S-031, “Verification of Lessee Compliance with State Lease, Section 11, Transfer, Assignment, or Other Disposition,” (March 12, 2002)

State Lease Section 18 – Reimbursement of State Expenses

- JPO Surveillance Report No. ANC-02-S-036, “Verification of Lessees’ Compliance With State Lease, Section 18, Reimbursement of State Expenses,” (March 12, 2002)

State Lease Section 22 – Duty of Lessees to Prevent or Abate

- JPO Assessment Report No. ANC-01-A-015, “Assessment of Compliance with ADF&G Requirements and Grant and Lease Stipulation 2.12, Restoration,” (November 2001)
- JPO Assessment Report No. ANC-01-011, “Assessment of Compliance With ADF&G Requirements and Grant and Lease Stipulation 2.5, Fish & Wildlife Protection,” (November 2001)
- JPO Assessment Report No. ANC 02-A-001, “Evaluation of Agreement and Grant of Right-of-Way and Right-of-Way Lease Stipulation 1.20, Health and Safety,” (February 2002)
- JPO Technical Report No. FBU-01-E-006, “Stipulation 2.7, Clearing,” (July 18, 2001)
- JPO Technical Report No. VMT-02-E-001, “Engineering Report on Berths 4 and 5, Tanker Vapor Control System, RCM Progress,” (April 1, 2002)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” pp. 21, 34-35, 37-38, (January 2001)
- JPO Letter No. 02-004-DG, to APSC, Re: “Closure of Notice, Compulsory Redesign of the Valdez Marine Terminal Vapor Control System, Letter No. 99-033-LB,” (February 11, 2002)
- JPO and Alyeska Pipeline Service Company Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- State and Federal Interagency and Alyeska Pipeline Service Company Report, “Joint After-Action Report for the TAPS Bullet Hole Response of October 2001,” (February 8, 2002)

State Lease Section 23 – Compliance With Notices to Proceed

- JPO Letter No. 97-074-JS, to APSC, Re: “JPO Policy to Implement Notice to Proceed (NTP) Process For Work on TAPS at the Valdez Marine Terminal, Pump Stations and the Mainline Pipe,” (October 7, 1997)
- JPO Technical Report No. FBU-02-E-001, “Compliance Verification with Notices to Proceed, Section 10 of the Federal Grant, and Section 23 of the State Lease,” (January 2002)
- JPO Assessment No. JPO-00-A-004, “Alyeska Pipeline Service Company, 1999 Flood Damage Repair Project, F-075,” (June 2000)
- JPO CMP Report, “Trans-Alaska Pipeline Construction Program 1999/2000,” (January 2001)

CHAPTER 3

- JPO Assessment Report No. ANC-02-A-007, “Federal Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Legal and Administrative Stipulations,” (March 2002)

Stipulation 1.2.3 - Responsibilities

- JPO and Alyeska Pipeline Service Company Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)

Stipulation 1.2.4 - Responsibilities

- JPO Surveillance Report No. JPO-98-GS-035, “Verification of Alyeska Compliance With Grant and Lease Stipulation 1.2.4, Permittee Responsibilities for Proper Authorization to Use Lands Outside the TAPS Right-of-Way,” (September 22, 1998)
- JPO Surveillance Report No. ANC-02-S-020, “Verification of Permittee/Lessee Compliance With Grant and Lease Stipulation 1.2.4, Responsibilities, Use or Occupancy of Federal and State Lands Not Within the Right-of-Way,” (March 12, 2002)

Stipulation 1.3.1 – Authorized Officer/State Pipeline Coordinator

- JPO CMP Report, “Trans-Alaska Pipeline Construction Program 1999/2000,” pp.33-34, (January 2001)

Stipulation 1.3.2 - Authorized Officer/State Pipeline Coordinator

- JPO Surveillance Report No. ANC-02-S-021, “Verification of Permittee/Lessee Compliance With Grant and Lease Stipulation 1.3.2, Authorized Officer/State Pipeline Coordinator,” (March 12, 2002)
- JPO Letter No. 01-008-DG, to APSC, Re: “Earthquake Monitoring System,” (May 8, 2001)
- JPO Letter No. 01-010-DG, to APSC, Re: “Stipulation 3.4.2.3, Fault Monitoring, Imposing Special Provisions Under Authority of Stipulation 1.3.2,” (March 16, 2001)
- JPO Letter No. 01-011-DG, to APSC, Re: “Stipulation 3.8, Glacier Surges, Imposing Special Provisions Under Authority of Stipulation 1.3.2,” (March 19, 2001)
- JPO Letter No. 01-012-DG, to APSC, Re: “Performance requirements for Depth of Cover at Buried Mainline Pipe Side-Bend and Over-Bend Locations, Imposing Special Provisions Under Authority of Stipulation 1.3.2,” (March 22, 2001)

Stipulations 1.4.2 and 1.4.4 - Common Agent of Permittees/Lessees

- JPO Surveillance Report No. ANC-02-S-022, “Verification of Permittee/Lessee Compliance With Grant and Lease Stipulation 1.4, Common Agent of Permittees/Lesseees,” (March 12, 2002)

Stipulations 1.5.2 and 1.5.3 - Authority of Representatives of Authorized Officer/State Pipeline Coordinator and Common Agent; Orders of Authorized Officer/State Pipeline Coordinator

- JPO Surveillance Report No. ANC-02-S-019, “Verification of Permittee/Lessee Compliance With Grant and Lease Stipulations 1.5.2 and 1.5.3, Authority of Representatives of Authorized Officer/Pipeline Coordinator and Common Agent, Orders of Authorized Officer/Pipeline Coordinator,” (March 12, 2002)

Stipulation 1.7 - Notices to Proceed

- JPO Technical Report No. ANC-02-E-001, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 1.7, Notices to Proceed,” (March 5, 2002)
- JPO Letter No. 97-074-JS, to APSC, Re: “JPO Policy to Implement Notice to Proceed (NTP) Process For Work on TAPS at the Valdez Marine Terminal, Pump Stations and the Mainline Pipe,” (October 7, 1997)
- JPO Letter No. 01-177-DG, to APSC, Re: “Technical Report JPO No. FBU-01-E-005, Revision 1, APSC Compliance With Stipulation 2.11, Use of Explosives,” (December 13, 2001)

Stipulation 1.9 - Antiquities and Historical Sites

- JPO Surveillance Report No. ANC-01-S-096, “Compliance With Grant and Lease Stipulation 1.9.1, Approval of an Archaeologist for Surveillance and Inspection of the Pipeline System for Archaeological Values,” (November 1, 2001)
- JPO Surveillance Report No. ANC-02-S-041, “Compliance with Stipulation 1.9, Subsections 1.9.2 and 1.9.3, Antiquities and Historical Sites,” (February 27, 2002)

- JPO Letter No. 01-176-DG, to APSC, Re: “Stipulation 1.9, Antiquities and Historical Sites, Approval of Archaeologist,” (December 10, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 01-17784, to AO and SPCO, Re: “Stipulation 1.9, Antiquities and Historical Sites, Archaeological Surveys,” (October 23, 2001)

Stipulation 1.10 - Completion of Use

- JPO Letter No. 99-073-JS, to APSC, Re: “Status of Ramped Down Pump Stations,” (August 19, 1999)
- Alyeska Pipeline Service Company, Government Letter No. 99-14938, Re: “JPO Letter No. 99-073-JS, Status of Ramped Down Pump Stations, August 19, 1999,” (September 30, 1999)

Stipulation 1.11 - Public Improvements

- JPO Technical Report No. FBU-01-E-001, Revision 1, “A Review of Alyeska’s Compliance Verification Relevant to Grant and Lease Stipulation 1.11.1, Public Improvements,” (October 15, 2001)
- Alyeska Pipeline Service Company, “TAPS Pipeline and Repair Manual (MR-48)”
Alyeska Pipeline Service Company, “TAPS Engineering Manual (PM-2001)”

Stipulation 1.12.4 - Regulation of Public Access

- JPO Assessment Report No. ANC-01-A-016, “Federal Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Stipulation 1.12, Regulation of Public Access,” (March 2002)

Stipulation 1.13.1 - Electronically Operated Devices

- JPO Technical Report No. FBU-01-E-003 Revision 1, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 1.13, Electronically Operated Devices,” (October 16, 2001)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s Operation of the Trans-Alaska Pipeline System,” p. 30, (February 1999)

Stipulation 1.14.1 - Camping, Hunting, Fishing and Trapping

- JPO Assessment Report No. FBU-01-E-007, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 1.14, Camping, Hunting, Fishing and Trapping,” first report dated (July 18, 2001), Revision 1, dated (December 18, 2001)
- JPO Letter No. 02-018-DG, to APSC, Re: “Stipulation 1.14.1, Requirement Clarification,” (March 8, 2002)
- U.S. Office of the Federal Register, Federal Register Notice, Volume 48, No. 90, FR Document No. 83-13071, “Trans-Alaska Pipeline System Right-of-Way, Notice from the U.S. Bureau of Land Management,” (May 16, 1983)

Stipulation 1.15.1 - Small Craft Passage

- JPO Technical Report No. FBU-01-E-004, Revision 1, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 1.15.1, Small Craft Passage,” (October 22, 2001)
- Alyeska Pipeline Service Company, “Design Basis Update Manual, (DB-180),” Table 2-30, pp. 2-63
U.S. Coast Guard Letter No.16590, to APSC, Re: “U.S. Coast Guard Permitted Bridge Structures,” (February 2, 1994)

Stipulation 1.16 - Protection of Survey Monuments

- JPO Technical Report No. FBU-01-E-008, Revision 1, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 1.16, Protection of Survey Monuments,” (January 18, 2002)
- JPO Surveillance Report No. FBU-01-S-013, “Surveillance of Activities Associated With APSC Project F-901, 2001 Mainline Corrosion Investigation,” (June 19, 2001)
- JPO Surveillance Report No. FBU-01-S-027, “Surveillance of Activities Associated With APSC Project F-200, Buried Check Valve Investigation: Project Activities at Check Valves 6, 7 and, 9,” (August 9, 2001)
- JPO Surveillance Report No. JPO-00-S-106, “Evaluation of APSC Compliance for Environmental Project F196, Check Valve 74 Replacement,” (September 18, 2000)
- JPO Surveillance Report No. JPO-00-S-129, “Evaluation of APSC Compliance With Environmental Project F-900, Mainline Corrosion Investigation at Phelan Creek, PLMP 592.79,” (November 5, 2000)
- Det Norske Veritas (DNV), “Progress Review Report, ROWR Compliance Audit of Alyeska Pipeline Service Company,” prepared for the Trans-Alaska Pipeline System Owners, Project No. 10561-C, Copy Number 1, (March 2001)
- Det Norske Veritas (DNV), “ROWR Compliance Audit of Alyeska Pipeline Service Company, Progress Review (Systems Finds) Report,” prepared for the Trans-Alaska Pipeline System owners project No. 10561-E (March 2002)

- Alyeska Pipeline Service Company, AL-00-G101, “Alaska Pipeline Monumentation Survey Plats,” Sheets 1-143, (November 1980)

Stipulation 1.17.1 - Fire Prevention and Suppression

- JPO Surveillance Report No. 97-GS-085, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 9,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-086, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 7,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-087, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 5,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-088, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 3,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-089, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 1,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-090, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 4,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-091, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Pump Station 12,” (May 25, 1998)
- JPO Surveillance Report No. 97-GS-092, “Verification of Compliance With Stipulation 1.17, Fire Prevention, Suppression, and Reporting, Valdez Marine Terminal,” (May 25, 1998)
- JPO Surveillance Report No. JPO-99-S-059, “Verification of APSC Compliance With Stipulation 1.17, Fire Prevention and Suppression, Protection of Pump Station 9 from the Donnelly Flats Wildfire,” (June 21, 1999)
- JPO Surveillance Report No. JPO-00-S-019, “Follow-up Surveillance for the Pump Station 9 Wildfire,” (April 1, 2000)
- JPO Technical Report No. VMT-01-E-001, “East Metering Fire Foam Test, Valdez Marine Terminal on April 26, 2001,” (May 7, 2001)
- JPO Assessment Report No. JPO-00-A-002, “TAPS Shutdown, Valve Replacement, Maintenance, and Pipeline Re-Start, September 11 and 12, 1999,” (September 1999)
- JPO Assessment Report No. ANC-02-A-001, “Evaluation of Agreement and Grant of Right-of-Way and Right-of-Way Lease Stipulation 1.20, Health and Safety,” (February 2002)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s TAPS Employee Safety Program,” pp. 2-3, (April 1998)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” pp. 30-34, (January 2001)
- State and Federal Interagency and Alyeska Pipeline Service Company Report, “Joint After-Action Report for the TAPS Bullet Hole Response of October 2001,” (February 8, 2002)

Stipulation 1.18.1 - Surveillance and Maintenance

- JPO Surveillance Report No. VMT-01-S-036, “Site Surveillance At Remote Gate Valve (RGV) 104, PLMP 677, Verification of Alyeska Pipeline Service Corporation (APSC) compliance with Grant and Lease Stipulation 1.18.1, Surveillance and Maintenance and Stipulation 1.21.1, Conduct of Operations,” (October 31, 2001)
- JPO Assessment Report No. JPO-00-A-001, “Alyeska Pipeline Service Company Compliance With Fish Passage and Related Environmental, Surveillance, Maintenance and Quality Program Requirements,” (February 2000)
- JPO CMP Report, “An Evaluation of Selected Portions of the TAPS Maintenance Program, January 1997-April 1999,” (April 1999)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s Operation of the Trans-Alaska Pipeline System,” (February 1999)
- JPO CMP Report, “Operation of the Trans-Alaska Pipeline 1999/2000,” p. 28-32, (February 2001)
- JPO Letter No. 02-012-DG, to APSC, Re: “Finding to Grant and Lease Stipulation 1.18.1 as Documented by VMT-01-S-036, Revision 1, Remote Gate Valve 104,” (March 6, 2002)
- JPO and Alyeska Pipeline Service Company Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- Alyeska Pipeline Service Company, “Integrity Monitoring Program Manual, (MP-166),” Section 2.09, “Access Road and Work Pad Bridge Monitoring,” (July 13, 2001)

- Alyeska Pipeline Service Company, Government Letter No. 00-16344, Re: “Closure of Corrective Action Request No. 00-002, Regarding the Lack of Processes and Documentation to Demonstrate Full Compliance With Grant Section 9 and Lease Section 16, and Stipulations 1.18.1, 1.18.3, and 2.5.1,” (October 4, 2000)
- U.S. Department of Transportation, Office of Pipeline Safety, Code of Federal Regulations, Title 49, Section 195.412
- Alaska Administrative Code (AAC), Title 18, Environmental Conservation, Chapter 75, Oil and Other Hazardous Substances Pollution Control (18 AAC 75.055(a)(3))

Stipulation 1.18.2 – Surveillance and Maintenance

- JPO CMP Report, “Operation of the Trans-Alaska Pipeline System 1999/2000,” (February 2001)

Stipulation 1.18.4 – Surveillance and Maintenance

- JPO Technical Report No. FBU-01-E-002, “A Review of Alyeska’s Compliance Relevant to Stipulation 1.19, Housing and Quarters,” (April 16, 2001)

Stipulation 1.20 - Health and Safety

- JPO Letter No. 01-171-DG, to APSC, Re: “Accident Investigation of the Valdez Marine Terminal Fatality of August 16, 2000,” (November 27, 2001)
- JPO Letter No. 01-191-DG, to APSC, Re: “Accident Investigation of the Valdez Marine Terminal Fatality of August 16, 2000, APSC Government Letter No. 01-18025, December 20, 2001,” (December 28, 2001)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s TAPS Employee Safety Program,” (April 1998)
- JPO and Alyeska Pipeline Service Company, Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- Alyeska Pipeline Service Company, Government Letter No. 01-18025, Re: “Accident Investigation of the Valdez Marine Terminal Fatality of August 16, 2000, JPO Request for Additional Information, Letter 01-171-DG, dated November 27, 2001,” (December 20, 2001)
- The Williams-Steiger Occupational Safety and Health (OSHA) Act, 29 U.S.C., Chapter 655, (1970)

Stipulation 1.21.1 - Conduct of Operations

- JPO Surveillance Report No. FBU-01-S-013, “Surveillance of Activities Associated With APSC Project F-901, 2001 Mainline Corrosion Investigation,” (June 19, 2001)
- JPO Technical Report No. VMT-02-E-001, “Engineering Report on Berths 4 and 5, Tanker Vapor Control System, RCM Progress,” (April 3, 2002)
- JPO Assessment Report No. VMT-01-A-002, “An Evaluation of Alyeska’s Improvement in Recognizing and Properly Communicate Safety-Critical Conditions at the Valdez Marine Terminal,” (November 27, 2001)
- JPO CMP Report, “Evaluation of Alyeska’s Pipeline Service Company’s Operation of the Trans-Alaska Pipeline System,” pp. 28-32, (February 1999)
- JPO CMP Report, “An Evaluation of Selected Portions of the TAPS Maintenance Program, January 1997-April 1999,” pp. 21, 28-35, (April 1999)
- JPO CMP Report, “Trans-Alaska Pipeline Construction Program 1999/2000,” pp. 4-5, (January 2001)
- JPO and Alyeska Pipeline Service Company Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- JPO Letter No. 02-004-DG, to APSC, Re: “Closure of Notice, Compulsory Redesign of the Valdez Marine Terminal, Vapor Control System, Letter No. 99-033-LB,” (February 11, 2002)
- JPO Letter No. 02-012-JS, to APSC, Re: “TAPS Cold Restart Study,” (March 14, 2002)
- JPO Letter No. 02-013-JS, to APSC, Re: “Alyeska Letter No. 02-18296, TAPS Cold Restart Study Functional Completion,” (March 14, 2002)
- Alyeska Pipeline Service Company, Government Letter No. 01-17077, Re: “Y2K Teleconference, March 26, 2001,” (May 1, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 02-18299, to transmit memorandum of agreement, Re: “Compliance Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (March 6, 2002)

Stipulation 2.1 - Environmental Briefing

- JPO Assessment Report No. FBU-01-A-002, “Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Stipulation 2.1.1, Environmental Briefing,” (July 2, 2001)

Stipulation 2.2 - Pollution Control

- Clean Air Act, as amended, 42 U.S.C. § 1857 *et seq.*
- Federal Water Pollution Control Act, as amended, 33 U.S.C. § 1321 *et seq.*
- Alyeska Pipeline Service Company, “Valdez Marine Terminal Tanker Vapor Control System Management Review,” (October 7, 1999)

Stipulation 2.3 - Buffer Strips

- JPO Assessment Report No. FBU-01-A-003, Revision 1, “Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Stipulation 2.3, Buffer Strips,” (December 6, 2001)
- Alyeska Pipeline Service Company, G-100 Alignment Sheet Summaries, “Pipeline Right-of-Way Acreage Audit Summary Report,” (May 21, 1977)
- U.S. Bureau of Land Management, Alaska State Office, Division of Pipeline, “Environmental Assessment Atlas, Proposed Trans-Alaska Pipeline,” compiled by Newell (Cy) Price, (July 1973)

Stipulation 2.4 - Erosion Control

- JPO Assessment Report No. ANC-02-A-002, “An Evaluation of Alyeska Pipeline Service Company’s Compliance with the Federal Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Stipulation 2.4, Erosion Control,” (January 2002)
- JPO Assessment Report No. ANC-01-A-013, “An Evaluation of Alyeska Pipeline Service Company’s Compliance With the Federal Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Stipulation 3.5, Slope Stability,” (December 1, 2001)
- JPO and Alyeska Pipeline Service Company, Memorandum of Agreement, “In the Matter of Continuous Improvement of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- Alyeska Pipeline Service Company, “Maintenance Operations Manual,” (EP-106)

Stipulation 2.5 - Fish and Wildlife Protection

- JPO Assessment Report No. JPO-00-A-001, “Alyeska Pipeline Service Company Compliance with Fish Passage and Related Environmental, Surveillance, Maintenance and Quality Program Requirements,” (February 2000)
- JPO Assessment Report No. ANC-01-A-011, “Assessment of Compliance With ADF&G Requirements and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 2.5, Fish and Wildlife Protection,” (November 2001)

Stipulation 2.6.1 - Purchase of Materials

- JPO Assessment Report No. ANC-01-A-005, “Assessment of Operations Material Sites, Surveillances Conducted August 2000,” (May 2001)
- JPO Assessment Report No. JPO-00-A-003, “Assessment of Operations Material Sites,” (May 2001)
- JPO Assessment Report No. 98-A-016, “Assessment of Operations Material Sites,” (October 1998)
- JPO Assessment Report No. ANC-01-A-009, “Assessment of Operations Material Sites,” (October 2001)
- JPO Letter No. 01-052-DW, to APSC, Re: “TAPS Assessment Report No. ANC-01-A-005, Assessment of Operations Material Sites,” (June 4, 2001)
- JPO Letter No. 01-045-DW, to APSC, Re: “TAPS Operation Material Sites, 100-2.1, 39-1.1 and 27-3N, Closure of JPO Finding 98-A-016-F/01,” (May 3, 2001)
- JPO Letter No. 02-009-MC, to APSC, Re: “OMS 27-3N, 39-1.1 and 100-2.1, Mining Plan Revisions, JPO Letter No. 01-145-DW and 01-052-DW,” (January 17, 2002)
- U.S. Bureau of Land Management Manual, Section 3600, Minerals Material Disposal, (May 25, 1988)
- U.S. Bureau of Land Management, Instruction Memorandum No. 2001-043, Subject: “Mineral Materials Inspection and Enforcement, Production Verification, and Appraisal Policy, Replacing IM. No. 99-021,” (November 29, 2000)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” pp. 27-28, 30-31, (January 2001)

- U.S. Department of the Interior, Code of Federal Regulations, Title 43, Section 3610
- U.S. Department of the Interior, Code of Federal Regulations, Title 43, Section 23
- Alyeska Pipeline Service Company, Government Letter No. 01-17968, Re: “Assessment of TAPS Operation Material Sites, Report No. ANC-01-A-009,” (December 10, 2001)

Stipulation 2.7 - Clearing

- JPO Technical Report No. FBU-01-E-006, “Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 2.7, Clearing,” (July 18, 2001)

Stipulation 2.8 - Disturbance of Natural Waters

- JPO Letter No. 01-089-DW, to APSC, Re: “Request for Authorization to Affect Four Beaver Dams, Pump Station 12 Asset Area, Pipeline Mileposts 680.1 to 764.8,” (July 6, 2001)
- JPO Letter No. 01-102-DW, to APSC, Re: “Request for Organization to Affect a Beaver Dam, Pump Station 12 Asset Area, Pipeline Milepost 736.13,” (August 8, 2001)
- JPO Letter No. 01-103-DW, to APSC, Re: “Request for Authorization to Affect a Beaver Dam, Pump Station 7 Asset Area, Pipeline Milepost 449.83,” (August 9, 2001)
- JPO Letter No. 01-104-DW, to APSC, Re: “Request for Authorization to Affect Two Beaver Dams, Pump Station 9 Asset Area, Pipeline Mileposts 562.35 and 596.75,” (August 9, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 01-17291, Re: “Request for Authorization to Affect Four Beaver Dams, Pump Station 12 Asset Area, Pipeline Mileposts 680.1 to 764.8,” (June 22, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 01-17406, Re: “Request for Organization to Affect a Beaver Dam, Pump Station 12 Asset Area, Pipeline Milepost 736.13,” (July 25, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 01-17397, Re: “Request for Authorization to Affect Two Beaver Dams, Pump Station 9 Asset Area, Pipeline Mileposts 562.35 and 596.75,” (July 26, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 01-17416, Re: “Request for Authorization to Affect a Beaver Dam, Pump Station 7 Asset Area, Pipeline Milepost 449.83,” (July 26, 2001)
- Rivers and Harbors Act, 33 U.S.C., 403, Section 10, (1899)
- Clean Water Act, as amended, U.S.C 33, (1972)
- Alaska Statute Title 16, Fish and Game, Section 16.05.840, Fishway Required
- Alaska Statute Title 16, Fish and Game, Section 16.05.870, Protection of Fish and Game

Stipulation 2.9 - Off Right-of-Way Traffic

- JPO Assessment Report No. ANC-01-A-006, “Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 2.9, Off Right-of-Way Traffic,” (July 2001)

Stipulation 2.10 - Aesthetics

- JPO Surveillance Report No. FBU-01-S-028, “Verification of APSC Compliance With Stipulation 2.10, Aesthetics, at PLMP 246, Dalton Highway Crossing,” (September 24, 2001)
- JPO Surveillance Report No. FBU-01-S-029, “Verification of APSC Compliance With Stipulation 2.10, Aesthetics, at PLMP 254, MP 159, Dalton Highway Crossing,” (September 24, 2001)
- JPO Surveillance Report No. FBU-01-S-030, “Verification of APSC Compliance With Stipulation 2.10, Aesthetics, at PLMP 397, Manley Road Crossing,” (August 11, 2001)
- JPO Surveillance Report No. FBU-01-S-031, “Verification of APSC Compliance With Stipulation 2.10, Aesthetics, at PLMP 456, Chena Hot Springs Road Crossing,” (August 11, 2001)
- JPO Surveillance Report No. FBU-01-S-032, “Verification of APSC Compliance With Stipulation 2.10, Aesthetics, at PLMP 563, Richardson Highway, MP243 Crossing,” (August 11, 2001)

Stipulation 2.11 - Use of Explosives

- JPO Technical Report No. FBU-01-E-005, “Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 2.11, Use of Explosives,” (November 2001)

Stipulation 2.12 - Restoration

- JPO Assessment Report No. ANC-01-A-015, “Assessment of Compliance with ADF&G Requirements and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 2.12, Restoration,” (November 2001)

Stipulation 2.13.1 - Reporting of Oil Discharges

- Federal Water Pollution Control Act, as amended, 33 U.S.C. § 1321 *et seq.*

Stipulation 2.13.2 - Restoration

- JPO Letter No. 94-231-T, to APSC, Re: “Stipulation 2.13, Spill Reporting Requirements,” (December 21, 1994)
- Alyeska Pipeline Service Company, “Environmental Protection Manual,” EN-43-1, Ed. 7, Rev. 0, (December 31, 2001)
- Alyeska Pipeline Service Company, “Pipeline Oil Discharge Prevention and Contingency Plan,” APSC Document No. CP-35-1, Edition 4, Rev. 0, Section 1.3.3, (December 31, 2001)

Stipulation 2.14 - Contingency Plans

- JPO Surveillance Report No. ANC-01-S-002, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Unannounced Oil Spill Response Exercise,” (June 7, 2001)
- JPO Surveillance Report No. ANC-01-S-003, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 6,” (June 21, 2001)
- JPO Surveillance Report No. ANC-01-S-004, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 5,” (June 21, 2001)
- JPO Surveillance Report No. ANC-01-S-005, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 4,” (June 21, 2001)
- JPO Surveillance Report No. ANC-01-S-006, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 3,” (June 21, 2001)
- JPO Surveillance Report No. ANC-01-S-007, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 2,” (June 21, 2001)
- JPO Surveillance Report No. ANC-01-S-008, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 1,” (June 21, 2001)
- JPO Surveillance Report No. ANC-01-S-015, “Verify Conformance With Approved Oil Discharge Prevention and Contingency Plan, Stipulation 2.14.3, Pump Station 12, Oil Spill Response Exercise,” (October 13, 2001)
- JPO Assessment Report No. ANC-02-A-010, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 2.13, Reporting of Oil Discharges; Stipulation 2.14, Contingency Plans; and Stipulation 3.11, Containment of Oil Spills,” (March 14, 2002)
- JPO Letter No.00-068-JH, to APSC, Re: “Drill Evaluation Report for Pipeline Reconnaissance Drill, P/L Segment 7, September 29, 2000,” (October 6, 2000)
- JPO Letter No. 01-014-CA, to APSC, Re: “Report on Unannounced Oil Spill Preparedness Exercises Conducted December 21 and 28, 2000,” (January 19, 2001)
- JPO Letter No. 01-109-DG, to APSC, Re: “Oil Discharge Prevention and Contingency Plan, Equipment Inspection Records Review at Pump Stations 1 Through 6, and Tabletop Exercise at Pump Station 5, Conducted May 29 Through June 1, 2001,” (June 7, 2001)
- JPO Letter No. 01-172-DG, to APSC, Re: “Annual Approval of the Pipeline Oil Spill Contingency Plan,” (April 4, 2002)
- U.S. Office of the Federal Register, Federal Register Notice, “National Oil Hazardous Substances Pollution Contingency Plan,” Volume 36 F.R., Document No.16215, (August 20, 1971)
- Alaska Department of Environmental Conservation, Letter to Alyeska Pipeline Service Company, File No. 306.50, Re: “Oil Discharge Prevention and Contingency Plan Equipment Inspection at Pump Station 12 on March 20, 2001, and Pump stations 7 and 9 on March 29 and 30, 2001,” (April 10, 2001)
- Alaska Department of Environmental Conservation Regulations, Title 18, Alaska Administrative Code, Section 75, Oil & Hazardous Substances Pollution Control
- Alyeska Pipeline Service Company, Government Letter No. 01-17176, Re: “ADEC Letter of April 10, 2001, Oil Discharge Prevention and Contingency Plan Equipment Inspection at Pump Station 12, March 20, 2001 and Pump Stations 7 and 9, March 29 and 30, 2001,” (May 23, 2001)
- Alyeska Pipeline Service Company, Government Letter No.01-17341, Re: “Status Update on Oil Spill Equipment PM Revisions, APSC Letter No. 01-17176, May 23, 2001, Oil Discharge Prevention and Contingency Plan Equipment,” (July 10, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 00-16399, Re: “Drill Evaluation Report for Pipeline Reconnaissance Drill, P/L Segment 7, JPO Letter 00-068-JH, October 6, 2000,” (October 19, 2000)
- U.S. Environmental Protection Agency, Code of Federal Regulations, Title 40, Protection of Environment, Part 112, Oil Pollution Prevention, (40 CFR 112)

- U.S. Department of Transportation, Office of Pipeline Safety, Code of Federal Regulations, Title 49, Transportation, Part 194, Response Plans for Onshore Oil Pipelines (49 CFR194)
- U.S. Coast Guard, Code of Federal Regulations, Title 33, Navigation and Navigable Waters, Part 154, Facilities Transferring Oil or Hazardous Material in Bulk (33 CFR 154)

Stipulation 3.2 - Pipeline System Standards

- U.S.A. Standard Code for Pressure Piping, ANSI B 31.4, "Liquid Petroleum Transportation Piping System"
- American Society of Mechanical Engineers (ASME), Gas Piping Standard Committee, "Guide for Gas Transmission and Distribution Piping System," (December 15, 1970)
- American National Standards Institute, (ANSI), C5.1-1969, "Lightning Protection Code-1968.17
- United States Code, Title 49, Transportation, Chapter 601
- U.S. Department of Transportation, Office of Pipeline Safety Regulations, Code of Federal Regulations, Title 49, Parts 190-199: Part 190, Pipeline Safety Programs and Rulemaking Procedures; Part 191, Transportation of Natural and Other Gas by Pipeline; Annual Reports, Incident Reports, and Safety Related Condition Reports; Part 192, Transportation of Natural and Other Gas by Pipeline: Minimum Federal Safety Standards; Part 193, Liquefied Natural Gas Facilities: Federal Safety Standards; Part 194, Response Plans for Onshore Oil Pipelines; Part 195, Transportation of Hazardous Liquids by Pipeline; Parts 196 and 197, Reserved; Part 198, Regulations for Grants to Aid State Pipeline Safety Programs; Part 199, Drug and Alcohol Testing
- U.S. Department of Transportation, Office of Pipeline Safety, "Notice of Probable Violation, Proposed Civil Penalty, and Proposed Compliance Order," CPF No. 5-2000-5018, (September 14, 2000)
- U.S. Department of Transportation, Office of Pipeline Safety, "Notice of Probable Violation and Proposed Compliance Order," CPF No. 5-2001-0012, (December 3, 2001)
- U.S. Department of Transportation, Office of Pipeline Safety, "Notice of Probable Violation, Proposed Civil Penalty and Compliance Order," CPF No. 5-2002-5003, (February 6, 2002)
- U.S. Department of Transportation, Office of Pipeline Safety, Letter No. CPF 5-2002-5001, (January 2, 2002)
- U.S. Department of transportation, Office of Pipeline Safety, "Notice of Probable Violation, Proposed Civil Penalty and Compliance Order," CPF No. 5-2000-5006, (February 10, 2000)
- U.S. Department of Transportation, Office of Pipeline Safety, "Notice of Probable Violation, Proposed Civil Penalty and Compliance Order," CPF No. 59502, (March 5, 1999)
- U.S. Department of Transportation, office of Pipeline Safety, Research and Special Programs Administration, Letter to BLM Authorized Officer, Re: "Summary of TAPS Non-Compliance and Enforcement Record as of February 2002," April 15, 2002.

Stipulation 3.2.2.1 – Pipeline System Standards

- JPO CMP Report, "An Evaluation of Selected Portions of the TAPS Maintenance Program, January 1997-April 1999," pp. 14-16, 25-26, 32-34, (April 1999)

Stipulation 3.2.2.3 – Pipeline System Standards

- JPO Surveillance Report No. VMT-01-S-035, "Verification of APSC Compliance With Stipulations 1.18.1, 1.20, and 1.3.2.1, Surveillance of the General Environmental/Safety/Integrity conditions at the Valdez Marine Terminal," (September 21, 2001)

Stipulation 3.2.2.4 – Pipeline System Standards

- JPO CMP Report, "Trans-Alaska Pipeline Construction Program 1999/2000," (January 2001)

Stipulation 3.2.2.5 – Pipeline System Standards

- JPO Surveillance Report No. JPO-00-S-026, "Corrosion Investigation Project F900, on Below-Ground Mainline Pipe, MP 710," (June 12, 2000)
- JPO Surveillance Report No. 99-S-097, "Installation of Stopples and Replacement of Remote Gate Valve, RGV-60, Project F064, PLMP 352," (September 17, 1999)
- JPO Technical Report No. JPO-00-E-029, "Corrosion Monitoring of Station Piping, Pump Station 9," (August 29, 2000)

Stipulation 3.2.2.6 – Pipeline System Standards

- Det Norske Veritas (DNV), "Progress Review Report, ROWR Compliance Audit of Alyeska Pipeline Service Company," prepared for the Trans-Alaska Pipeline System Owners, Project No. 10561-C, Copy Number 1, (March 2001)

- Alyeska Pipeline Service Company, Government Letter No. 01-18019, Re: “Det Norske Veritas Compliance Audit,” (December 20, 2001)

Stipulation - 3.2.3.1- Pipeline System Standards

- JPO Surveillance Report No. 00-S-73, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 329.3, No Name Creek,” (September 26, 2000)
- JPO Surveillance Report No. 00-S-74, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 398.6, Tolovana Creek,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-83, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 437.1, Washington Creek,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-84, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 438.4, Dome Creek,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-85, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 442.2, Treasure Creek,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-86, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 472.4, Moose Creek 2,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-87, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 473.6, Moose Creek 1,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-88, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 476.5, French Creek 4,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-89, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 476.7, French Creek 3,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-90, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 477.2, French Creek 1,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-91, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 477.2, French Creek 2,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-92, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 483.9, French Creek 0,” (November 13, 2000)
- JPO Surveillance Report No. 00-S-93, “Verify Repairs of Access Road and Work Pad Bridge to close Audit Action Item No. 50528, PLMP 490.8, Little Salcha River,” (November 13, 2000)

Stipulation 3.3.1 - Construction Mode Requirements

- JPO Technical Report No. ANC-02-E-003, “Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 3.3, Construction Mode Requirements,” (February 28, 2002)
- JPO Surveillance Report No. JPO-98-GS-068, “Atigun Pass Heat Pipe/Insulation Box Performance and Maintenance, Stations PLMP 166.1 through 167.4, Verification of Compliance With Stipulation 3.31, Construction Mode Requirements,” (October 5, 1998)
- JPO Surveillance Report No. JPO-99-S-111, “Verify Installation of Thermistor Strings in Insulated Box Area of Atigun Pass, JPO-98-068-F/01 & NCR 4500, PLMP 166.1” (October 20, 1999)
- JPO CMP Report, “Operation of the Trans-Alaska Pipeline 1999/2000,” p.16, (January 2001)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” p.16, (January 2001)
- JPO Letter No. 01-012-DG, to APSC, Re: “Performance Requirements for Depth of Cover at Buried Mainline Pipe Side-Bend and Over-Bend Locations, Imposing Special Provisions Under Authority of Stipulation 1.3.2,” (March, 22, 2001)

Stipulation 3.4 - Earthquakes and Fault Displacements

- JPO Technical Report No. ANC-02-E-002, “Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 3.4, Earthquakes and Fault Displacements,” (February 26, 2002)
- Alyeska Pipeline Service Company, “Seismic Program Audit No.01-09,” (October 12, 2001)
- Alyeska Pipeline Service Company, Government Letter No.01-7768, Re: “Seismic Program Audit No. 01-09,” (October 19, 2001)
- Alyeska Pipeline Service Company, “TAPS Earthquake Preparedness Program (EEP) Management Plan,” (July 16, 2001)
- Arthur D. Little, Inc., “Trans-Alaska Pipeline System Assessment Task Force, Final Report to the Owners of the Trans-Alaska Pipeline System,” a report prepared for the TAPS Owner Companies, Acorn Park, Cambridge, Massachusetts, (July 1994)

- Quality Technology Company, Owen Thero, “Audit of Trans-Alaska Pipeline System,” a report prepared for the U.S. Bureau of Land Management, Lebo, Kansas, (November 5, 1993)

Stipulation 3.4.1.2 - Earthquakes and Fault Displacements

- JPO Letter No. 01-050-DG, to APSC, Re: “Earthquake Monitoring System Testing,” (May 11, 2001)
- JPO Letter No. 01-008-DG, to APSC, Re: “Earthquake Monitoring System,” (May 8, 2001)
- JPO Letter No. 01-189-DG, to APSC, Re: “Earthquake Monitoring System Finding, ANC-01-E-008-F/01,” (December 19, 2001)
- JPO Surveillance Report No. JPO-99-S-106, “Verification of Earthquake Monitoring System Operations, Functionality of all EMS Stations as Monitored at the Operations Control Center,” (October 26, 1999)
- JPO Surveillance Report No. JPO-00-S-001, “Verification that Operational Problem of DSMA at Valdez Documented by Surveillance Report No. JPO-99-106 Was Fixed and Verification That Other Stations Are Still Operational,” (January 7, 2000)
- JPO Technical Report No. ANC-01-E-008, “Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 3.4.1.2, Performance of the APSC Earthquake Monitoring System,” (December 18, 2001)
- Alyeska Pipeline Service Company, Government Letter No. 02-18229, Re: “JPO Letter No. 01-188-DG, dated December 19, 2001, Subject: Earthquake Monitoring System Finding, ANC-01-E-008-F/01,” (January 14, 2002)

Stipulation 3.4.2.2 - Fault Displacements

- Alyeska Pipeline Service Company, “Fault Crossing Design Assessment, Final Report,” by Michael Baker Jr., Inc. (February 8, 2002)

Stipulation 3.4.2.3 – Fault Displacements

- JPO Surveillance Report No. ANC-01-S-010, “Stipulation 3.4.2.3, Fault Displacement Monitoring, Denali Fault,” (July 6, 2001)
- JPO Letter No. P001-TAPS-3853, (December 29, 1988)
- JPO Letter No. 01-010-DG, to APSC, Re: “Stipulation 3.4.2.3, Fault Monitoring, Imposing Special Provisions Under Authority of Stipulation 1.3.2,” (March 16, 2001)
- U.S. Department of the Interior, Letter No. P001-TAPS-3853, (September 1977)
- Alyeska Pipeline Service Company, “Fault Crossing Design Assessment Final Report,” (February 8, 2002)

Stipulations 3.5 - Slope Stability and 3.9 - Construction and Operations

- JPO Assessment Report No. ANC-01-A-012, “An Evaluation of Alyeska Pipeline Service Company’s Compliance with Federal – State Agreement and Grant of Right-of-Way And State Right of Way Lease, Stipulation 3.9, Construction and Operations,” (December 1, 2001)
- JPO Assessment Report No. ANC-01-A-013, “An Evaluation of Alyeska Pipeline Service Company’s Compliance with the Federal Agreement and Grant of Right-of-Way and State Right-of-Way Lease, Stipulation 3.5, Slope Stability,” (December 1, 2001)
- JPO Letter No. 01-009-FC, to APSC, Re: “Slope Stability Performance Requirements Pursuant to Stipulation 3.2.1.2,” (February 7, 2001)
- JPO Letter No. 01-110-DG, to APSC, Re: “Aboveground System Additional Requirements Pursuant to Stipulation 3.2.1.2,” (June 29, 2001)
- JPO Letter No. 01-157-DG, to APSC, Re: “Request for Information on TAPS Aboveground Pipe and Soil Conditions,” (November 5, 2001)
- JPO Letter No. 99-063-JH, to APSC, Re: “Corrective Action Plan for Slope Stability and Aboveground Pipeline Maintenance on Squirrel Creek Slopes,” (August 11, 1999)
- JPO Letter No. 00-012-WT, to APSC, Re: “Approval of Design Basis Request and Order Closure for Squirrel Creek,” (January 4, 2001)

Stipulation 3.6 - Stream and Flood Plain Crossings and Erosion

- JPO Technical Report No. JPO-99-E-018, “Summary Report on the River/Floodplain Crossings of the Trans-Alaska Pipeline System,” (August 27, 1999)
- JPO Technical Report No. FBU-02-E-003, “Federal Agreement and Grant of Right-of-Way and Right-of-Way Lease, Stipulation 3.6, Stream and Flood Plain Crossings and Erosion and State of Alaska Right-of-Way Lease for the Trans-

Alaska Pipeline, Section 40, Incorporates Stipulation 3.6 of the Federal Agreement and Grant of Right-of-Way Lease,” (January 2002)

- JPO and Alyeska Pipeline Service Company, Memorandum of Agreement, “In the Matter of Continuous Improvement, of the Alyeska Compliance Systems, Quality Program, Change Management, and Corrective Action Processes,” (February 28, 2002)
- U.S. Army Corps of Engineers Bulletin 52-8, Part 1

Stipulation 3.7.1 - Sea Waves

- JPO Assessment Report No. VMT-01-A-001, “An Evaluation of Alyeska Pipeline Service Company’s Compliance With Agreement and Grant of Right-of-Way, Stipulation 3.7, Sea Waves,” (May 4, 2001)

Stipulation 3.8 - Glacier Surges

- JPO Surveillance Report No. FBU-S-01-033, “Verify APSC Compliance With Special Requirements of Stipulation 3.8 as Stated in JPO Letter No. 01-011-DG,” (January 7, 2002)
- JPO Surveillance Report No. JPO-97-GS-043, “Verification of Glacier Monitoring and Aerial Surveillance Activities, Pump Station 9,” (November 21, 1997)
- JPO Technical Report No. FBU-01-E-009, Revision 1, “A Review of Alyeska’s Compliance Verification Relevant to Stipulation 3.8, Glacier Surges,” (November 2001)
- JPO Assessment Report No. 97-A-018, “An Evaluation of Alyeska’s Glacier Monitoring Procedures to Determine the Effectiveness of the Surveillance Systems to Give Adequate Warning of Impending Surges on Any Glacier That Could Damage the Pipeline System,” (December 23, 1997)
- JPO CMP Report, “Evaluation of Alyeska Pipeline Service Company’s Operation of the Trans-Alaska Pipeline System,” (February 1999)
- JPO Letter No. 01-011-DG, to APSC, Re: “Stipulation 3.8, Glacier Surges, Imposing Special Provisions Under Authority of Stipulation 1.3.2,” (March 19, 2001)
- Alyeska Pipeline Service Company, “System Integrity Monitoring Procedure Manual,” MP-166-2.06, Sections 5.2.2.C and 5.2.2.D.2
- Alyeska Pipeline Service Company, Government Letter No. 01-17204, Re: “Stipulation 3.8, Glacier Surges, Imposing Special Provisions Under Authority of Stipulation 1.3.2, JPO Letter No. 01-011-DG, 3/19/2001, CART No. 4169, A/R No. 31000176,” (May 31, 2001)

Stipulation 3.10 - Pipeline Corrosion

- JPO Technical Report No. JPO-00-E-021, “TAPS Corrosion History,” (June 22, 2000)
- JPO Technical Report No. JPO-00-E-028, “TAPS Corrosion Control Engineering Report (November 2, 2000)
- JPO CMP Report, “Trans-Alaska Pipeline Maintenance Program 1999/2000,” pp. 17-19, (January 2001)
- U.S. Department of Transportation, Office of Pipeline Safety, Title 49 Code of Federal Regulations, Section 195

Stipulation 3.11 - Containment of Oil Spills

- Alaska Administrative Code (AAC), Title 18, Environmental Conservation, Chapter 75, Oil and Other Hazardous Substances Pollution Control (18 AAC 75.055(a)(3))

